

Change of Prospects
REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date Sept 20 184 1
on the Mr Manacles Master Waisall
Tonnage 574 Built at Calcutta When built 1802
By whom built _____ Owners Thomas Ward
Port belonging to London Destined Voyage Seymour
If Surveyed Afloat or in Dry Dock Mill hall Dock

Original Survey, No. _____ Dated _____ 1839 Classed X. A. 1

Port London

REPAIRS Caution from the copper up and the copper
very largely repaired with between 5 & 600 sheets
New Iron Rigging & new main Mast

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Top-sides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Sheers	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

Good *Good* *Good & efficient*

General Observations and Opinion, In my opinion this ship is eligible to run on
as clapped X. A.

The Amount of Fee.....£ : : is received by me,

Committee's Minute _____ 18

Character assigned _____

James Bayley
© 2019

Lloyd's Register
Foundation