

807

REPORT of SURVEY for REPAIRS.

& Change of Names

No. 507 Survey held at Sidon Date October 5th 1841
 on the By Sovereign Master W. H. Mason
 Tonnage 146 Built at Peru Scotia When built 1838
 By whom built 123 Owners Hammings
 Port belonging to Sidon Destined Voyage Peru
 If Surveyed Afloat or in Dry Dock in Devon Dry Dock

Original Survey, No. 2470 Dated 1838 Classed A A 1

REPAIRS At the present time caused from the heel overle of the
beards (as usual), all defective are shifted -

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkutting	Wales	Masts, Yards, &c. <u>Good</u>
Plank Shears	Counter	Sails <u>Sufficient</u>
Waterways	Plank & Treennails (Outside to the Water Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion From her general good appearance I am of opinion she
may retain her present class



The Amount of Fee £ : 10 : is received by me, (a Office

Committee's Minute 12th October 1841

Character assigned A A 1

Lloyd's Register Foundation