

REPORT of SURVEY for REPAIRS.

No. 453 Survey held at London Date Sept 17 1841
 on the Maritime Master Robson
 Tonnage 576 Built at Calcutta When built 1809
 By whom built _____ Owners Robson & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Leinchile Dock

Original Survey, No. 218, 1207 Dated 1839 Classed B. 1
241, 302, 4035, 5542, 5685,
 Port London

REPAIRS New Upper Deck of Baltic Deal - New Plankheads, Waterways
Comings & Hold Beams & 3 half inch Upper Deck
New Ceiling Fore Decks from the lower to the Upper Deck
& 15g Bars Septentrian Shifts - & 45 Felling Timber put
in - The Upper & lower Deck fastenings renewed with
the exception of a few bolts to the Lower Deck
New Main Mast

Present Condition of the

Decks <u>New 18 1/2 1841</u>	Transoms <u>Good</u>	Windlass <u>Refitted</u>
Upper Deck Beams & Fastenings <u>New 1841</u>	Timbers of the Frame <u>15g Bars Sept 1841</u>	Capstan <u>Good</u>
Lower Deck Beams & Fastenings <u>New 1841</u>	Top-sides <u>Good</u>	Pumps <u>"</u>
Spirketting <u>New 1841</u>	Wales <u>"</u>	Masts, Yards, &c. <u>New Plankhead</u>
Plank Sheers <u>do</u>	Counter <u>"</u>	Sails <u>Good</u>
Waterways <u>do</u>	Plank & Treennails <u>"</u>	Cables <u>"</u>
Hatchway Comings <u>do</u>	Rudder <u>"</u>	Anchors No. of <u>"</u>
Breasthooks <u>Good</u>	Copper <u>Ref 1841</u>	Standing & Running Rigging <u>Refitted</u>

General Observations and Opinion, My opinion the ship is capable of service
as before, B. 1

The Amount of Fee £ 3 is received by me, George Bayley

Committee's Minute 15th October 1841

Character assigned To the Assistant Surveyor

© 2019

Lloyd's Register
Foundation