

ANNUAL SURVEYS.

8065
JH

No. 603 Survey held at London Date Oct 20th 1841
 on the Schooner Clementina Master Pavey
 Tonnage 131 Built at Spanish When built 1814
 By whom built _____ Owners Water H
 Port belonging to London Destined Voyage Antislad
 If Surveyed Afloat or in Dry Dock Four & aft ways

Original Survey, No. 12715 Port of London Classed 1/1 A 1

The Surveyor is required to state the present Condition of the

Decks <u>very good</u>	Transoms _____	Capstan _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame <u>1 not seen</u>	Pumps _____
Lower Deck Beams & Fastenings <u>also</u>	Topsides _____	Masts, Yards, &c. _____
Spirkettling <u>good</u>	Wales _____	Sails <u>good &</u>
Plank Shears <u>London</u>	Counter <u>good</u>	Cables <u>sufficient</u>
Waterways _____	Plank and Treennails (Outside to the Water's Edge.) _____	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
Breasthooks _____	Windlass _____	Copper _____

General Observations and Opinion, At the present time can't see the Bottom & Reel the
 as required by the Instructions, the Rudder Irons. The vessel is in a very efficient
state & should remain as classed

Committee Minute 26th October 1841
 Character assigned 1/1 Antislad Water & Clark

No. 262 Survey held at London Date Oct 19th 1841
 on the Barque Catharine Elizabeth Master Merritt
 Tonnage 209 Built at London When built 1813
 By whom built _____ Owners Farjieu
 Port belonging to London Destined Voyage S. Vincente
 If Surveyed Afloat or in Dry Dock the Reel Irons

Original Survey, No. 971, 2703 Port of London Classed 1/1 A 1
3870, 4375, 6377, 6924, 7571

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms _____	Capstan _____
Upper Deck Beams & Fastenings <u>good & fine</u>	Timbers of the Frame <u>good when seen</u>	Pumps _____
Lower Deck Beams & Fastenings _____	Topsides _____	Masts, Yards, &c. _____
Spirkettling _____	Wales _____	Sails <u>good &</u>
Plank Shears _____	Counter <u>good</u>	Cables <u>sufficient</u>
Waterways <u>good</u>	Plank and Treennails (Outside to the Water's Edge.) _____	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
Breasthooks _____	Windlass _____	Copper _____

General Observations and Opinion, This vessel is in a good & sufficient state &
 as required by the Instructions, in my opinion should remain as classed

Committee Minute 20th October 1841
 Character assigned 1/1 Water & Clark