

REPORT of SURVEY for REPAIRS.

No. ³⁸⁷ Survey held at Sunder Date October 9th 1841
 on the By Grecian Master B. W. Richards
 Tonnage 212 Built at Yarmouth When built 1824
 By whom built _____ Owners Richardson
 Port belonging to Sunder Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Somekin Dock

Original Survey, No. 2954, 3697, Dated 1841 ⁶⁷⁹³ Classed A.1. B.1. C.1.
 Port of Sunder

REPAIRS At the present time bottom stripped, several new beams
from planks on each side of the ceiling, where the turn of the sides
stripped with Green Oak, three pair of additional hanging iron
knives to the Deck beams, & two pair to the Side beams
caulked from the keel to the gunwale and Appended over paper

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Copstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <u>Well</u>
Plank Shears	Counter	Sails <u>Good</u>
Waterways	Plank and Trenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>over paper Oct. 1841</u>	Standing & Running Rigging

General Observations and Opinion, The timbers were exposed very sound, and appear in
a very efficient state for the safe conveyance of Dry
and perishable cargo to & from all parts of the World
and may continue A.1. B.1. C.1.

The Amount of Fee.....£ 1 : : is received by me, A. G. Richards

Committee's Minute 29th October 1841

Character assigned A.1. B.1. C.1. Certificate issued