

ANNUAL SURVEYS.

80/3

No. 276 Survey held at London Date October 26 1844
 on the Br Rapid Master R Thomas
 Tonnage 276 Built at Trent When built 1833
 By whom built W. G. & Co Owners W. G. & Co
 Port belonging to Liverpool Destined Voyage Lancaster
 If Surveyed Afloat or in Dry Dock West India Dock

Original Survey, No. 1040 Port of Liverpool Classed 10 A 1

The Surveyor is required to state the present Condition of the

| | | |
|-------------------------------|--------------------------------|----------------------------|
| Decks | Breasthooks | Capstan |
| Upper Deck Beams & Fastenings | Transoms | Pumps |
| Lower Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Spirkettling | Topsides | Sails |
| Plank Shears | Wales | Cables |
| Waterways | Plank and Treennails | Anchors No. of |
| Hatchway Comings | (Outside to the Water's Edge.) | Standing & Running Rigging |
| | Rudder | Copper |
| | Windlass | |

General Observations and Opinion, At the present time bottom can be & is in good condition to continue as before
 as required by the Instructions, and is in good condition to continue as before

Committee Minute 184

Character assigned 10 A 1

No. 294 Survey held at Liverpool Date October 25 1844
 on the Br Acasta Master J. Ryle
 Tonnage 294 Built at Cheshire When built 1834
 By whom built W. G. & Co Owners Liverpool & Manchester Ship Co
 Port belonging to Liverpool Destined Voyage Liverpool
 If Surveyed Afloat or in Dry Dock Fletcher Dock

Original Survey, No. 3244 Port of Liverpool Classed 10 A 1

The Surveyor is required to state the present Condition of the

| | | |
|-------------------------------|--------------------------------|----------------------------|
| Decks | Breasthooks | Capstan |
| Upper Deck Beams & Fastenings | Transoms | Pumps |
| Lower Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Spirkettling | Topsides | Sails |
| Plank Shears | Wales | Cables |
| Waterways | Plank and Treennails | Anchors No. of |
| Hatchway Comings | (Outside to the Water's Edge.) | Standing & Running Rigging |
| | Rudder | Copper |
| | Windlass | |

General Observations and Opinion, Bottom examined & the Masts & Stays can be & is in good condition to continue as before
 as required by the Instructions, and is in good condition to continue as before
hatches examined & the respective ones
proven out

Committee Minute 29th October 1844

Character assigned 10 A 1