

ANNUAL SURVEYS.

8090

No. 537 Survey held at London Date Oct 25 1841
 on the Mc Ludlow Master Johnson
 Tonnage 287 Built at Sunderland When built 1832
 By whom built _____ Owners Graham
 Port belonging to London Destined Voyage Antigua
 If Surveyed Afloat or in Dry Dock Smiths Dry Dock

Original Survey, No. 132, 3583 Port of London April 1841 Classed 1A-1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Top-sides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, The Rigging down from hauling - to have new after
 as required by the Instructions, shrouds - broad sheeting stripped off upper course
upper course caulked - & re-sheeted with yellow metal
keelson bolts reclined - gibboard broke two & found good

Committee Minute 2nd November 1841 Yellow metal repaired - good - many
 Character assigned 1A-1 very fair eligible to remain as classed 1A-1

No. Survey held at London Date Oct 25 1841
 on the Ship to Robert Peel Master _____
 Tonnage _____ Built at Sunderland When built 1841
 By whom built Greenwell Owners Scotchmen
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dowson Dry Dock

Original Survey, No. _____ Port of Sunderland 1841 Classed _____

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Top-sides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, Bottom holed and sheathed with yellow metal
 as required by the Instructions, she appears eligible to the class 1A-1, some without

Security has been recommended to be put upon the transport
in the Port, should it be required by the Board
 Committee Minute _____ 1841
 Character assigned _____