

Continuation 8101 REPORT of SURVEY for REPAIRS.

Survey held at Londra Date 1 November 1841
 the By Adelaide Master Townsend
 nage 124 Built at Bideford When built 1831
 whom built _____ Owners Bunsford
 rt belonging to Bideford Destined Voyage Coaster
 Surveyed Afloat or in Dry Dock in the ways

Original Survey, No. 41 Dated _____ Classed 10 A 1
 at Bristol, Bideford 116, 189.

REPAIRS
 Some plank shifted at Bideford and were re-nailed by the former report
 The upper and lower Deck boards, the planks through which they
 pass the waterways beams, Halse timbers, Knight heads, Breast
 hooks, transoms, the floors and keelson, the plankenig outside
 from the keel up, the ceiling inside, the frame and inner surface
 of the outside plank where it could be seen, the Decks plomings
 all in good condition. The sheer is unaltered and the keel
 straight.

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spikketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging
General Observations and Opinion,	<p>Some of the bolts were driven out for inspection and found good. Is now in a good condition and may in our opinion be continued <u>3 A 1</u> from 1841</p>	

The Amount of Fee £ 2 : - : is received by me, H. B. Clark

Committee's Minute 9th November 1841

Character assigned 3 A 1