

ANNUAL SURVEYS.

8135

No. 18 Survey held at Sidon Date Apr 9th 1841
 on the Ship Dartmouth Master Jacks
 Tonnage 635 Built at Dartmouth When built 1839
 By whom built _____ Owners J. Cook
 Port belonging to Sunderland Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock East India Dock

Dartmouth 293
 Original Survey, No. 1139 Port of Sidon 1141 Classed 11A1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Top-sides	Masts, Yards, &c.
Spirketting	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Stowage Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlasses	Copper

General Observations and Opinion, Bottom examined in the dry dock and appears in every
 as required by the Instructions, respect in an efficient state to continue as before
[Signature]

Committee Minute 16th November 1841
 Character assigned [Signature]

No. 291 Survey held at Sidon Date October 9th 1841
 on the Ship Charles Brooke Master J. Hunt
 Tonnage 298 Built at Exeter When built 1825
 By whom built _____ Owners Smith & Co
 Port belonging to Sidon Destined Voyage St Vincent
 If Surveyed Afloat or in Dry Dock East India Dock

Original Survey, No. 1139 Port of Sidon 1141 Classed 11A1
2423, 3712, 4598, 6000

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Top-sides	Masts, Yards, &c.
Spirketting	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Stowage Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlasses	Copper

General Observations and Opinion, Is a very efficient state both in the Hull & Stowage
 as required by the Instructions, and may retain her present Character
[Signature]

Committee Minute 16th November 1841
 Character assigned [Signature]

© 2019
 Lloyd's Register
 Foundation

LONB11-0431