

ANNUAL SURVEYS.

81/48

No. 663 Survey held at Sidon Date Nov 8th 1844
 on the By Charlotte Marie Master Weather
 Tonnage 150 Built at Porte When built 1821
 By whom built _____ Owners Putteng
 Port belonging to Sidon Destined Voyage Gambia
 If Surveyed Afloat or in Dry Dock Ward India Dock

Original Survey, No. 2367 Port of Sidon 4670, 4703, 6738, 7464 Classed A.1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Good</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Spirketting <u>"</u>	Wales <u>"</u>	Sails <u>"</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>16 1/2 fms of Chain</u>
Waterways <u>"</u>	Plank and Treennails <u>"</u> (Outside of the Water's Edge.)	Anchors No. of <u>2 brass & 2 Specimen</u>
Hatchway Coverings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>Good in 1830</u>

General Observations and Opinion, The vessel appears in good condition for the safe conveyance
 as required by the Instructions, being suitable, but having no steam power, I am
of opinion should be classed A.2

Committee Minute 10th Nov 1844

Character assigned A.2

No. 412 Survey held at Sidon Date Nov 31st 1844
 on the Ship Clifford Master J. Sharpe
 Tonnage 461 Built at Marjport When built 1840
 By whom built _____ Owners Sharpe & Co
 Port belonging to Somerset Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Carlton & Grange Dock

Original Survey, No. _____ Port of Marjport 1840 Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Good</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>"</u>	Masts, Yards, &c. <u>"</u>
Spirketting <u>"</u>	Wales <u>"</u>	Sails <u>"</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>Not found</u>
Waterways <u>"</u>	Plank and Treennails <u>"</u> (Outside of the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Coverings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>Good in 1841</u>

General Observations and Opinion, At the present time bottom is kept, masted, and the
 as required by the Instructions, vessel is in good condition, and is
ready for service.

Committee Minute 184

Character assigned _____

Lloyd's Register
Foundation