

# Change of Property REPORT of SURVEY for REPAIRS.

No. 560 Survey held at London Date November 1841  
 on the Ship Buckinghamshire Master Thomas E. H. Granger  
 Tonnage 1469 Built at Bombay When built 1816  
 By whom built agents Messrs & Co Owners Cowagers  
 Port belonging to London ? Destined Voyage Bombay  
 If Surveyed Afloat or in Dry Dock Pier Dock R. & S. Dock

Original Survey, No. 4542 Dated 1840 Classed A. 1

Port London

REPAIRS Docked - examined copper smooth & good requiring  
only 7 sheets to repair - To caulk counter and  
manger - Rep & ceiling - Can haulings must  
fast. Hails - Rigging down touchhauling

## Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topside	Pumps
Spirkelling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treemails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of <u>21 1/2</u> & <u>16</u>
Breasthooks	Copper <u>Good</u>	Standing & Running Rigging <u>Good</u>

## General Observations and Opinion.

Wants a new Anchor which is to be supplied  
before sailing - In my opinion she is capable  
to remain as classed.

The Amount of Fee.....£ 5 : - - is received by me, George Bayley

Committee's Minute 30th November 1841

Character assigned Fit to service

Lloyd's Register  
Foundation