

# ANNUAL SURVEYS.

8182

No. 532 Survey held at London Date 26 Nov 1841  
 on the Ship Lydia Master Steyn  
 Tonnage 313 Built at Shildon When built 1840  
 By whom built W. & A. Wood Owners Wood  
 Port belonging to London Destined Voyage Canada  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1459 Port of Newcastle, Lon 7059

Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper <u>Blue</u> ?

General Observations and Opinion, as required by the Instructions, In a good state of different conditions and may want repairs Continued

Committee Minute 3rd November 1841

Character assigned 10 A 1

No. 532 Survey held at London Date 26 Nov 1841  
 on the Ship Thomas Coates Master Wade  
 Tonnage 313 Built at Shildon When built 1840  
 By whom built W. & A. Wood Owners Woods  
 Port belonging to London Destined Voyage China  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_

Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, as required by the Instructions, The Masts, Rigging for previous repairs & the fore part of upper deck party decked over, look a good Continued

Committee Minute \_\_\_\_\_ 1841

Character assigned \_\_\_\_\_