

ANNUAL SURVEYS.

8211

No. 40 Survey held at London Date Nov-20th 1841
 on the Schooner Sapphire Master Thompson
 Tonnage 78 Built at Shawich When built 1840
 By whom built _____ Owners Archib
 Port belonging to Shawich Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Mountain ways

Original Survey, No. 210 Port of Shawich, Lon 7/54 Classed 11A1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame <u>not seen</u>	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails <u>good & sufficient</u>
Plank Shears	Counter <u>good</u>	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper <u>Line</u>

General Observations and Opinion, At the present time pointed the Line sheathing
 as required by the Instructions, which was a little corroded.
The vessel is in an efficient state & should remain as Classed

Committee Minute 7th December 1841

Character assigned 11A1

No. 491 Survey held at London Date Nov. 23rd 1841
 on the Schooner Royal Eagle Master Allen
 Tonnage 142 Built at Little Hampton When built 1824
 By whom built _____ Owners London & Waterford Ship Co
 Port belonging to London Destined Voyage Waterford
 If Surveyed Afloat or in Dry Dock Home & aft ways

Original Survey, No. 36,353 Port of London, 10th 13/4, Lon 6/66 Classed *A1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame <u>good when seen</u>	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails <u>good & sufficient</u>
Plank Shears	Counter <u>good</u>	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks <u>not seen</u>	Windlass	Copper

General Observations and Opinion, This vessel is in good condition and may
 as required by the Instructions, remain as classed

Committee Minute 7th December 1841

Character assigned 11A1



© 2019

Lloyd's Register
Foundation