

REPORT of SURVEY for REPAIRS.

8353

No. 626 Survey held at London Date January 1. 7. 11. 1842
 on the Bk Mary Laing Master Arthur
 Tonnage 316 Built at P. Laing, Sunderland When built 1834
 By whom built P. Laing Owners Laing & P. Laing
 Port belonging to Sunderland Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock West India Dock

Sunderland 27,
 Original Survey, No. 2388, 3028, Dated 4553, Classed 6 R. 1
 Port of London Sunderland 1507, London 6822.

REPAIRS At the present time, new piece of Stern Post from the 10 feet mark upwards, new Rudder, an additional knuckle between the upper & lower deck, caulked from the keel to the waterway, steam screws examined & a general overhaul in the rigging.

Jan 7 19. 1842 - Fletcher Wray - Examined & repaired metal - good & smooth

Present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Windlass <u>Good</u>
Upper Deck Beams & Fastenings <u>Sound</u>	Timbers of the Frame <u>Sound when seen</u>	Capstan <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Pumps <u>"</u>
Spirkettling <u>Good</u>	Wales <u>"</u>	Masts, Yards, &c. <u>"</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Sails <u>Well stowed</u>
Waterways <u>"</u>	Plank & Treennails <u>Good</u> (Outside to the Water's Edge)	Cables <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>Good</u>	Anchors No. of <u>"</u>
Breasthooks <u>Sound</u>	<u>Survey 4th 1039</u>	Standing & Running Rigging <u>Good</u>

General Observations and Opinion, Is in a very efficient state, for the safe conveyance of dry & perishable cargo to & from all parts of the West & may be classed R. 1 with the best vessels

The Amount of Fee.....£ 2 : - is received by me, George Bayley
 Committee's Minute 20 Aug 1842
 Character assigned R. 1, Intimate

© 2019

Lloyd's Register Foundation

LONG12-0176