

# ANNUAL SURVEYS.

839

No. 116 Survey held at London Date Feb 4 1842  
 on the B<sup>n</sup> Matilda Master Morgan  
 Tonnage 275 Built at Amsterdam When built 1834  
 By whom built \_\_\_\_\_ Owners Luckin  
 Port belonging to London Destined Voyage Drumman  
 If Surveyed Afloat or in Dry Dock Dowson Dock

Original Survey, No. 1074, 2421, Port of London Jan 1841 Classed 10A1  
3123, 3560, 5932, 6732, 7636, 7656,

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper <u>up good at present</u>

General Observations and Opinion, In my opinion this ship is eligible to remain  
 as required by the Instructions, as classed 10A1

Committee Minute 8th February 1843

Character assigned 10A1

No. 545 Survey held at London Date Jan 7 1842  
 on the B<sup>n</sup> Unity Master Hamer  
 Tonnage 152 Built at St B When built 1830  
 By whom built \_\_\_\_\_ Owners Atkinson  
 Port belonging to Liverpool Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Blackwall Dock

Original Survey, No. 2699, 3536, Port of Liverpool July 1841 Classed 4A1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c. <u>Excellent Hand doubtful</u>
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper <u>up 1842</u>

General Observations and Opinion, Caulked from keel to keel and resheathed with yellow  
 as required by the Instructions, metal to water in my opinion is eligible to remain classed 4A

Replanned with 4th & 5th masts will be further examined then George Bayley

Committee Minute 8th February 1843

Character assigned 4A1



© 2019

Lloyd's Register  
Foundation



July 7

4 Annual

1. *Riparii*

3. S

6