

# ANNUAL SURVEYS.

8485

No. <sup>194</sup> Survey held at Lt M W M Date 28 February 184 2  
 on the Sch<sup>r</sup> Mm Maria Master Asbora  
 Tonnage 207 Built at Southampton When built 1840  
 By whom built - Owners J. Jackson  
 Port belonging to Southampton Destined Voyage Alexandria  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 81 Port of Southampton, Lon 7295 Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Do</u>	Pumps
Lower Deck Beams & Fastenings <u>Do</u>	Topsides <u>Do</u>	Masts, Yards, &c. <u>Good</u>
Spirkettling <u>Good</u>	Wales <u>Do</u>	Sails <u>Sufficient Good</u>
Plank Shears <u>Do</u>	Counter <u>Do</u>	Cables <u>Do</u> <u>Do</u>
Waterways <u>Do</u>	Plank and Treenails <u>Do</u> (Outside to the Water's Edge.)	Anchors No. of <u>Do</u> <u>Do</u>
Hatchway Comings <u>Do</u>	Rudder <u>Do</u>	Standing & Running Rigging <u>Do</u>
Breasthooks <u>Do</u>	Windlass <u>Do</u>	Copper <u>Good</u>

General Observations and Opinion,  
 as required by the Instructions,

Is in the most efficient condition and  
may remain as classed

Committee Minute 14th March 184 2

Character assigned 12 A 1

No. <sup>101</sup> Survey held at London Date 1st March 184 2  
 on the Sch<sup>r</sup> Eclipse Master Hore  
 Tonnage 109 Built at Southampton When built 1823  
 By whom built - Owners Hore & Co  
 Port belonging to Heter Destined Voyage East  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 146, 7437 Port of London Classed A. 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame <u>Do when new</u>	Pumps
Lower Deck Beams & Fastenings <u>Good</u>	Topsides <u>fair as can be seen</u>	Masts, Yards, &c. <u>Good</u>
Spirkettling	Wales <u>Do</u> <u>Do</u>	Sails <u>Very Good</u>
Plank Shears <u>Requires</u>	Counter <u>Do</u> <u>Do</u>	Cables <u>Do</u> <u>Do</u>
Waterways <u>Repairs</u>	Plank and Treenails <u>Good</u> (Outside to the Water's Edge.)	Anchors No. of <u>Sufficient Good</u>
Hatchway Comings	Rudder <u>Do</u>	Standing & Running Rigging
Breasthooks	Windlass <u>Do</u>	Copper

General Observations and Opinion,  
 as required by the Instructions,

Specially surveyed and found to want  
part new sheer strake, part new waterways & plank  
thiers & some ceiling which is intended to be done on

Committee Minute 14th March 184 2

Character assigned 10th May

Special A 1.0



~~Lead Sub Centre~~  
22 July 1942

Reduced to 141.

ahb

*[Faint, mostly illegible handwritten notes in pencil or light ink, possibly bleed-through from the reverse side. Some words like "Cable", "141", and "142" are faintly visible.]*



© 2019

Lloyd's Register  
Foundation