

REPORT of SURVEY for REPAIRS.

Change of Property 8540

No. 586 Survey held at London Date 10 March 1842
 on the Ship Bazarah Purchase Master Ferris
 Tonnage 531 Built at Calcutta When built 1810
 By whom built _____ Owners Ferris
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Fletcher's Dock

Original Survey, No. 1119, 2303, Dated 1840 Classed A. 1
 Port London 3459, 4914, 6823.

REPAIRS

~~Copper~~ Yellow metal repaired - smooth & good - 2 pieces of Saltskin fitted to keel generally examined

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,

Every opinion this ship is eligible to remain as clasped being fit for the conveyance of dry and perishable cargoes to & from all part of the world - & to be clasped A. 1

The Amount of Fee £ 3 : - : - is received by me,

George Bayley

Committee's Minute 29th March 1842

Character assigned

A. 1 Antarctic



Lloyd's Register
Foundation

LON 612-0370