

# REPORT of SURVEY for REPAIRS.

No. 8717 Survey held at LONDON Date Feb 18 18 57  
 on the Barth Schellgren Master \_\_\_\_\_  
 Tonnage 513 Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners J. Fletcher  
 Port belonging to LONDON Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Fletcher Dock

Original Survey, No. \_\_\_\_\_ Dated \_\_\_\_\_ Vol. \_\_\_\_\_ Classed \_\_\_\_\_  
 Port \_\_\_\_\_

## Repairs

*At the present time shipped cancelled  
 but to be & re-appears to be on Paper  
 In good condition*  
*J. Bayley*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,  
 as required by the Instructions,



© 2019

The Amount of Fee.....£ : : is received by me,  
 Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_  
 Character assigned \_\_\_\_\_

Lloyd's Register  
 Foundation