

# ANNUAL SURVEYS.

8750

No. 1033 Survey held at London Date May 13<sup>th</sup> 1842  
 on the 2c Alice Master W. Ward  
 Tonnage 455 Built at Whitby When built 1813  
 By whom built \_\_\_\_\_ Owners Chapman & Co  
 Port belonging to London Destined Voyage London  
 If Surveyed Afloat or in Dry Dock Plattin Dry Dock

Original Survey, No. 284, 375 Port of London Classified A.

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms	Capstan
Upper Deck Beams & Fastenings <u>General inspection</u>	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings <u>Don't enter</u>	Topsides <u>Inspection at Hull</u>	Masts, Yards, &c.
Spirkettling	Wales <u>Good</u>	Sails
Plank Shears <u>Don't enter</u>	Counter <u>Don't enter</u>	Cables
Waterways <u>Don't enter</u>	Plank and Treennails <u>Don't enter</u>	Anchors No. of
Hatchway Comings <u>Good</u>	Rudder <u>Good</u>	Standing & Running Rigging
Breasthooks <u>Don't enter</u>	Windlass <u>Good</u>	Copper <u>Don't enter</u>

General Observations and Opinion, There is a considerable movement on the Hold Beam Posts as required by the Instructions, at the Waterway down and Butts aloft. Ceiling is very insufficient round fastenings. Recommended to shift Plank next waterway and additionally both through the waterway into the Deck - which will tend to prevent the sagging of the Waterway beams. The repairs required to entitle this Ship to remain as classed being 14 by ten seconds.

Committee Minute 24<sup>th</sup> May 1842

Character assigned Reduced 1<sup>st</sup> Class  
George Bayley  
W. Ward

No. \_\_\_\_\_ Survey held at London Date May 13<sup>th</sup> 1842  
 on the Ship Athenian Master Mann  
 Tonnage 513 Built at Sunderland When built 1842  
 By whom built J. Gales Owners Koulinin  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Dowson Dry Dock

Original Survey, No. 1165 Port of Sunderland Classified 10 A1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treennails <u>(Outside to the Water's Edge)</u>	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, This Ship's Standards & additional Hold Beams Shaves as required by the Instructions, put in and properly fastened as recommended. Bottom sound and sheathed with Yellow Metal on plate 18 by 1. This in my opinion entitles to the Class 10 A1.

Committee Minute 24<sup>th</sup> May 1842

Character assigned 10 A1  
George Bayley  
W. Ward

May 11  
 12 Amount  
 2 Return  
 2 Amount  
 12



© 2019

Lloyd's Register  
Foundation