

ANNUAL SURVEYS.

8804

No. _____ Survey held at London Date May to June 4 1842
 on the Bj Brilliant Master Geo P Johnston
 Tonnage 240 Built at Workington When built 1828
 By whom built _____ Owners Mercant
 Port belonging to Liverpool Destined Voyage Cuba
 If Surveyed Afloat or in Dry Dock Liverpool Dock

Original Survey, No. 308, 385 Port of Liverpool Dock 1840 Classed F.F. No. 1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Top-sides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge)	Anchor's No. of
Hatchway Coverings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, After Caution has been taken - Head
as required by the Instructions,
re-fastened - since the date of last report it appears that
the bar has Spain somewhat but in - seen now in safe
state for the safe conveyance of any and suitable cargo to
Journal of the state of the vessel should be

Committee Minute 7th June 1842
 Character assigned F.F. No. 1 George Bayley

No. _____ Survey held at London Date June 3rd 1842
 on the Bt Anna Master _____
 Tonnage 188 Built at Spurwich When built 1831
 By whom built W Bayley Owners Genly
 Port belonging to Southampton Destined Voyage Liverpool
 If Surveyed Afloat or in Dry Dock Walthamstow Dock

Original Survey, No. 1728 Port of London June 1831 Classed 122-1

The Surveyor is required to state the present Condition of the

Lis 2112, Lon 753, 8776.

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Top-sides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge)	Anchor's No. of
Hatchway Coverings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, Caution throughout and sheathed with yellow metal
as required by the Instructions,
of the under water iron pieces - these slightly
brannish as clipped 1831

Committee Minute 7th June 1842
 Character assigned F.F. No. 1 George Bayley