

ANNUAL SURVEYS.

8821

No. 129 Survey held at London Date May 18 20 June 9 1842
on the 13th John Tomkinson Master Hutchinson
Tonnage 261 Built at Kincardine When built 1840
By whom built _____ Owners Rimmer
Port belonging to Liverpool Destined Voyage _____
If Surveyed Afloat or in Dry Dock Liverpool Dock St. Katherine's Dock

Original Survey, No. 3827 Port of Liverpool January 1840. Classed 6A1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings <u>See</u>	Timbers of the Frame <u>See</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>See</u>	Topsides <u>See</u>	Masts, Yards, &c. <u>New 1842</u>
Spirkettling <u>See</u>	Wales <u>See</u>	Sails <u>See</u> <u>good</u>
Plank Shears <u>See</u>	Counter <u>See</u>	Cables <u>Efficient</u>
Waterways <u>See</u>	Plank and Treennails <u>See</u> (Outside to the Water's Edge.)	Anchors No. of <u>See</u>
Hatchway Comings <u>See</u>	Rudder <u>See</u>	Standing & Running Rigging <u>New 1842</u>
Breasthooks <u>See</u>	Windlass <u>See</u>	Copper <u>various</u> <u>about 1842</u>

General Observations and Opinion Restored within - now refitted - carried aloft
as required by the Instructions, This vessel is built with Larch and presents a
very fine appearance throughout & is eligible in
my opinion to remain as classed 6A1

Committee Minute 10th June 1842

Character assigned 6A1 See George Bayley
See See

No. 170 Survey held at London Date May 4 June 6 1842
on the 13th John Tomkinson Master Hutchinson
Tonnage 240 Built at Whitehaven When built 1836
By whom built _____ Owners Brother & Co
Port belonging to Whitehaven Destined Voyage Liverpool
If Surveyed Afloat or in Dry Dock Whitehaven Harrold Bros

Original Survey, No. 212 Port of Whitehaven 1837. Classed 6A1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps <u>Good</u>
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c. <u>See</u>
Spirkettling	Wales	Sails <u>See</u>
Plank Shears	Counter	Cables <u>See</u>
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of <u>28A</u> <u>1st 16</u>
Hatchway Comings	Rudder	Standing & Running Rigging <u>Good</u>
Breasthooks	Windlass	Copper <u>See</u>

General Observations and Opinion, Stuffed carried kept up. Sheathed ypon paper now
as required by the Instructions, within - from opinion she is eligible to remain
as classed 6A1 - with the figure 1 - the additional
iron anchor is supplied according to the instructions

Committee Minute 10th June 1842

Character assigned 6A1 See George Bayley
See See