

## REPORT of SURVEY for REPAIRS.

8837

No. 113 Survey held at London Date May 26, 27, 28, 30, 31 June 1, 2, 3, 4, 1842  
 on the Ship Crested Master Pike  
 Tonnage 529 Built at Bristol When built 1835  
 By whom built Hillhouse & Co Owners Hillhouse & Co  
 Port belonging to Bristol Destined Voyage London, China  
 If Surveyed Afloat or in Dry Dock Rotated Dry Dock Ship now at Gravesend  
waiting for departure

Original Survey, No. 1478, 230 Dated \_\_\_\_\_ Classed RA1

Port Bristol & Liverpool No. 3800

REPAIRS - This Ship was docked for examination on the 24<sup>th</sup> May. the following found good  
 smooth she was under shell on the 28<sup>th</sup> during up the ribs the hull of  
 the main mast was discovered to be defective <sup>in</sup> further examination <sup>the</sup> ~~detected~~  
 keelson proved to be undermined from premature decay -  
 (found)  
 all the Ceiling, and Brunt Works having been removed below the  
 Low Deck the Stowage - Transfer of Opium - The piece of keelson  
 & three timbers, a number of 1<sup>st</sup> & 2<sup>nd</sup> & 3<sup>rd</sup> long timbers were  
 removed - and the Dry Rot entirely eradicated in every part  
 when any traces of it could be detected, by shifting the  
 timbers ~~affected~~ infected by it - New Ceiling, & Brunt Works,  
 & transoms from keel to keel from Foremast forward -  
 New Main and Foremast - Rigging refitted

## Present Condition of the

Decks	<u>Good</u>	Transoms	<u>Good</u>	Windlass	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Do</u>	Timbers of the Frame	<u>Do</u>	Capstan	<u>Do</u>
Lower Deck Beams & Fastenings	<u>Do</u>	Topsides	<u>Do</u>	Pumps	<u>Good</u>
Spirkettling	<u>Do</u>	Wales	<u>Do</u>	Masts, Yards, &c.	<u>New Main &amp; Fore Mast</u>
Plank Shears	<u>Do</u>	Counter	<u>Do</u>	Sails	<u>Good</u> <sup>out &amp; in</sup>
Waterways	<u>Do</u>	Plank and Trunnels (Outside the Water's Edge)	<u>Do</u>	Cables	<u>Do</u>
Hatchway Coverings	<u>Do</u>	Rudder	<u>Do</u>	Anchor No. of	<u>3. 1. 1</u>
Breasthooks	<u>3. 1. 1</u>	Copper	<u>Do</u>	Standing & Running Rigging	<u>Refitted</u>

## General Observations and Opinion,

In my opinion the defects are completely removed  
 the Ship is efficient & seaworthy as before RA1

The Amount of Fee £ 3 is received by me,

Committee's Minute 14 June 1842

Character assigned RA1

Special Repairs £ 3. 5

© 2019 Lloyd's Register Foundation