

ANNUAL SURVEYS.

8816

No. 1215 Survey held at London Date 13 June 1842
 on the Ship Vanguard Master _____
 Tonnage 242 Built at Sunderland When built 1840
 By whom built _____ Owners Clark & Co
 Port belonging to London Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1836 Port of Sunderland London Classed 8A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>do</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>"</u>	Sails <u>As Stuffed</u>
Plank Shears <u>do</u>	Counter <u>"</u>	Cables <u>do do</u>
Waterways <u>do</u>	Plank and Treennails <u>"</u> <small>(Outside to the Water's Edge.)</small>	Anchors No. of <u>do do</u>
Hatchway Comings <u>do</u>	Rudder <u>"</u>	Standing & Running Rigging <u>do do</u>
Breasthooks <u>do</u>	Windlass <u>"</u>	Copper _____

General Observations and Opinion,
 as required by the Instructions, Appears throughout in good and efficient
Condition and may remain as classed

Committee Minute 17th June 1842
 Character assigned 8A1

No. 123 Survey held at London Date 13 June 1842
 on the Ship Victoria Master Gunter
 Tonnage 120 Built at Cape Breton When built 1838
 By whom built _____ Owners Gunter
 Port belonging to Gibraltar Destined Voyage Gibraltar
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 184 Port of Gibraltar Classed 4A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>do</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings _____	Topsides <u>do</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treennails <u>do</u> <small>(Outside to the Water's Edge.)</small>	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper _____

General Observations and Opinion,
 as required by the Instructions, Is in good Condition and may remain
as classed

Committee Minute 17th June 1842
 Character assigned 4A1