

REPORT of SURVEY for REPAIRS.

88/49.

No. 145 Survey held at London Date May 30th 1 June 1842
 on the Schooner, Swallow Master Strangerat Birtley
 Tonnage 116 Built at Gibraltar When built 1826
 By whom built _____ Owners Doak
 Port belonging to London Destined Voyage St. Michaels
 If Surveyed Afloat or in Dry Dock Bombay Docks

Original Survey, No. 1174 Dated 2241, 3084, 4147, 4335, 4473, 5017, 7063. Classified A. 1
 Port London

REPAIRS

At the present time
 Shifter 1 seal on the Larboard side on the Station
 side next the waterways, & 2 planks on each
 side in the wales. Could rise from the rollers
 to waterways;

Present Condition of the

Decks <u>in good condition</u>	Transoms <u>not seen</u>	Windlass <u>Good</u>
Upper Deck Beams & Fastenings <u>fair</u>	Timbers of the Frame <u>about good</u>	Capstan <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>good</u>	Pumps <u>"</u>
Spirkettling <u>Good</u>	Wales <u>"</u>	Masts, Yards, &c. <u>"</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Sails <u>Good and</u>
Waterways <u>"</u>	Plank and Treennails <u>"</u> (Outside to the Water's Edge)	Cables <u>sufficient</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Anchors No. of <u>"</u>
Breasthooks <u>fair</u>	Copper <u>"</u>	Standing & Running Rigging <u>good</u>

General Observations and Opinion,

The vessel is in a fair & efficient state
not to carry any perishable cargo. It is my
opinion should remain as classed A. 1

The Amount of Fee.....£ — : 10 : — is received by me,

Committee's Minute 21st June 1842

Character assigned Not seen before

Lloyd's Register
 Foundation