

REPORT of SURVEY for REPAIRS.

No. 441 Survey held at LONDON Date 24 June 184 7
 on the Schr Highland Lad Master Pearritt
 Tonnage 113 Built at Farmouth When built 1830
 By whom built — Owners Pearritt
 Port belonging to Mristol Destined Voyage Mristol
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 634, 2525 Dated —

Classed Common 341

Port Liverpool, Lon 7705.

REPAIRS

Present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Windlass <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>—</u>	Copstan <u>—</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>—</u>	Pumps <u>—</u>
Spirkettling <u>Good</u>	Wales <u>—</u>	Masts, Yards, &c. <u>—</u>
Plank Sheers <u>—</u>	Counter <u>—</u>	Sails <u>Sufficient Hoop</u>
Waterways <u>—</u>	Plank and Treennails <u>—</u> (Outside to the Water's Edge)	Cables <u>do</u> <u>do</u>
Hatchway Comings <u>—</u>	Radder <u>—</u>	Anchors No. of <u>do</u> <u>do</u>
Breasthooks <u>—</u>	Copper <u>Good</u>	Standing & Running Rigging <u>do</u> <u>—</u>

General Observations and Opinion, It is in good sufficient condition and may
be used as a ship.

The Amount of Fee.....£ — : 10 : — is received by me, —

Committee's Minute 8th July 184 7

Character assigned Class 3 A 1

R. Penman

© 2019

Lloyd's Register
Foundation