

8964  
S.  
LB

Original Survey, No. 2337, 5028 Dated \_\_\_\_\_ Classed 7E.1

Present Condition of the		Transoms		Windlass	
Decks	Good		Good as when seen		New
Upper Deck Beams & Fastenings	"	Timbers of the Frame	"	Capstan	Good
Lower Deck Beams & Fastenings	"	Topsides	"	Pumps	"
Spirketting	"	Wales	"	Masts, Yards, &c.	Two Bizen New
Plank Shears	"	Counter	"	Sails	
Waterways	"	Plank and Treennails	"	Cables	Good & sufficient
		(Outside to the Water's Edge)		Anchors	No. of
Hatchway Comings	"	Rudder	"	Standing & Running Rigging	see hauls
Breasthooks	New	Copper	On the Cabin		

General Observations and Opinion, *The novel is now in an official State, for the*  
*the late conveyance of the Specimens of the novel to all*  
*parts of the world. In my opinion should remain as*  
*classical as with the historic*

The Amount of Fee.....£ / : - is received by me, *[Signature]*  
Committee's Minute *passed August 18 1872*  
Character assigned *1st. Asks for record repair*