

ANNUAL SURVEYS.

8909

No. 23 Survey held at London Date July 16th 1842
 on the Brigge Harold Master Wilson
 Tonnage 127 Built at Yarmouth When built 1810
 By whom built _____ Owners Fenwick
 Port belonging to London Destined Voyage Sidney
 If Surveyed Afloat or in Dry Dock Scrubbed Deck

W

Original Survey, No. 428 Port of Yarmouth Classed 12 A 5

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Not seen</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>good when seen</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkutting <u>"</u>	Wales <u>"</u>	Sails <u>"</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>2 bolted frames</u>
Waterways <u>"</u>	Plank and Treencails <u>"</u> <small>(Outside to the Water's Edge.)</small>	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>1/4 lb. Substained</u>

General Observations and Opinion,
as required by the Instructions,

The vessel is in good Condition & in my
Opinion should remain as classed

Committee Minute 5th August 1842

Character assigned 12 A 5 W

No. 168 Survey held at London Date July 22nd 1842
 on the Brig African Master Newman
 Tonnage 470 Built at Sheeham When built 1836
 By whom built _____ Owners Hustan
 Port belonging to London Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock Trounham Slip

W

Original Survey, No. 18 Port of Sheeham, Sea 3824, 6063 Classed 11 A 4

The Surveyor is required to state the present Condition of the


Decks <u>repaired good</u>	Transoms <u>good when seen</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>good when seen</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>1 good</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkutting <u>"</u>	Wales <u>"</u>	Sails <u>"</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>2 bolted frames</u>
Waterways <u>"</u>	Plank and Treencails <u>"</u> <small>(Outside to the Water's Edge.)</small>	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>1/4 lb. good</u>

General Observations and Opinion,
as required by the Instructions,

At the present time the vessel is in good Condition & in my
Opinion should remain as classed

Committee Minute 5th August 1842

Character assigned 11 A 4 W



© 2019 Lloyd's Register Foundation