

ANNUAL SURVEYS.

9021

No. 1118 Survey held at London Date August 10th 1842
 on the Brk Cypriotes Master W. Deane
 Tonnage 326 Built at Sunderland When built 1831
 By whom built _____ Owners Trueman & Co
 Port belonging to London Destined Voyage Ceylon
 If Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 1098 Port of Sunderland 1841 Classed G M 1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms _____	Capstan <u>good</u>
Upper Deck Beams & Fastenings <u>good & firm</u>	Timbers of the Frame _____	Pumps _____
Lower Deck Beams & Fastenings <u>"</u>	Topsides _____	Masts, Yards, &c. _____
Spirketting <u>good</u>	Wales _____	Sails <u>Wet & good</u>
Plank Shears <u>"</u>	Counter <u>good</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treennails <small>(Outside to the Water's Edge.)</small>	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder _____	Standing & Running Rigging <u>good</u>
Breasthooks <u>"</u>	Windlass _____	Copper <u>yellow metal good 1842</u>

General Observations and Opinion, Bottom examined, Masts & Blocks shakes caulked,
 as required by the Instructions, & is in a very efficient state to receive her present cargo

Committee Minute 2nd September 1842
 Character assigned 1 A 1

No. 153 Survey held at London Date August 23rd 1842
 on the Brk Irish Master J. B. Brain
 Tonnage 264 Built at Burport When built 1839
 By whom built _____ Owners Spaight & Co
 Port belonging to Semenich Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 6939 Port of London 1840 Classed M V 12 A S

The Surveyor is required to state the present Condition of the

Decks _____	Transoms _____	Capstan _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Pumps _____
Lower Deck Beams & Fastenings _____	Topsides _____	Masts, Yards, &c. _____
Spirketting _____	Wales _____	Sails <u>Wet</u>
Plank Shears <u>good</u>	Counter <u>good</u>	Cables <u>good</u>
Waterways _____	Plank and Treennails <small>(Outside to the Water's Edge.)</small>	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
Breasthooks _____	Windlass _____	Copper <u>1840 Spaight August 1842</u>

General Observations and Opinion, At the present time stripped, caulked, and offered
 as required by the Instructions, Irish in a very efficient state to continue her present cargo

Committee Minute 2nd September 1842
 Character assigned 12 A 1

© 2017 Lloyd's Register Foundation