

ANNUAL SURVEYS.

9053

No. ⁵²⁵ Survey held at London Date 14 Sept 1842
 on the B² Selway Master Johnson
 Tonnage 224 Built at Sunderland When built 1842
 By whom built _____ Owners E Graham
 Port belonging to Newcastle Destined Voyage Antigua
 If Surveyed Afloat or in Dry Dock Lineholm ways

Original Survey, No. 2134 Port of Sunderland March 1842 Classed 9A1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirketting	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthoos	Windlass	Copper

General Observations and Opinion, 9th Metal - Smooth & good - repaired one
 as required by the Instructions, sheet - Am of opinion that sheet is able to
remain as clasped 9A1

Committee Minute 16th September 1842

Character assigned 9A1

George Bayley

No. ⁵²⁶ Survey held at London Date 14 Sept 1842
 on the B² Mandingo Master Burgin
 Tonnage 217 Built at Sunderland When built 1827
 By whom built _____ Owners St Bonnett
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Fauling Dock

Original Survey, No. 700277 Port of London

10th Classed F.1
cont 1837 - 3 years A1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirketting	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthoos	Windlass	Copper

General Observations and Opinion, 9th and repaired Copper - Am of opinion that
 as required by the Instructions, sheet is able to remain as clasped F.1

Committee Minute 16th September 1842

Character assigned F.1

George Bayley