

ANNUAL SURVEYS.

9081

No. 343 Survey held at London Date Sept 24th 26 1842
 on the Bk Robert Myers Master Others
 Tonnage 312 Built at Glasgow When built 1837
 By whom built _____ Owners _____
 Port belonging to Liverpool Destined Voyage Canada
 If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 3731/107 Port of Liverpool Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Sound & secure</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Spirkettling <u>Good</u>	Wales <u>Good</u>	Sails <u>Well found</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Cables <u>Good</u>
Waterways <u>Good</u>	Plank and Treennails <u>Good</u> (Outside to the Water's Edge.)	Anchors No. of <u>2 heavy 1 iron 2 light</u>
Hatchway Coverings <u>Good</u>	Rudder <u>Good</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>Good</u>	Windlass <u>Good</u>	Copper <u>Good</u>

General Observations and Opinion, Ship a very efficient state in the Hull & Rigging
 as required by the Instructions, is deficient in lower masts of which notice has been given

Committee Minute 30th September 1842

Character assigned 12 A 2

No. 13 Survey held at London Date Sept 27th 1842
 on the Bk Earl of Harcourt Master J. Fox
 Tonnage 253 Built at Hull When built 1836
 By whom built _____ Owners Surrells
 Port belonging to Whitehaven Destined Voyage Singapore
 If Surveyed Afloat or in Dry Dock Afloat in the Harb

Original Survey, No. 1405 Port of Whitehaven Classed 11 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Good</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Spirkettling <u>Good</u>	Wales <u>Good</u>	Sails <u>Good</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Cables <u>Good</u>
Waterways <u>Good</u>	Plank and Treennails <u>Good</u> (Outside to the Water's Edge.)	Anchors No. of <u>3</u>
Hatchway Coverings <u>Good</u>	Rudder <u>Good</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>Good</u>	Windlass <u>Good</u>	Copper <u>Good</u>

General Observations and Opinion, Ship a very efficient state and may retain her
 as required by the Instructions, present state

Committee Minute 30th September 1842

Character assigned 11 A 1

Lloyd's Register
Foundation