

ANNUAL SURVEYS.

9112

No. 533 Survey held at Sidon Date Sept 30 184 2
 on the By Mary Dick Master J. McDonald
 Tonnage 170 Built at Tessobry When built 1839
 By whom built _____ Owners McDonald
 Port belonging to Dysart Destined Voyage Port-Jamais
 If Surveyed Afloat or in Dry Dock Sidon Dock

Original Survey, No. 1785 Port of Sidon 1840 Classed 5 A 1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Captain
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirketting	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, Ship in a very good condition both in the Hull & as required by the Instructions, She may retain her present Plg

Committee Minute 7th October 184 2

Character assigned 5 A 1

No. _____ Survey held at Sidon Date 1 September 184 2
 on the St. Marshing of Bute Master H. J. Allen
 Tonnage 190 Built at Dysart When built 1839
 By whom built _____ Owners Burdett
 Port belonging to Cardiff Destined Voyage Constantinople
 If Surveyed Afloat or in Dry Dock Sidon Dock

Original Survey, No. 1112 Port of Bristol 1840 Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Captain
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirketting	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, Ship in very high state of efficiency, and appears in as required by the Instructions, all repairs eligible to retain her present Plg

Committee Minute 7th October 184 2

Character assigned 12 A 1

© 2019

Lloyd's Register Foundation