

ANNUAL SURVEYS.

9113

No. 1023 Survey held at Londra Date October 5 1842
 on the Bk. Mission Master Maillard
 Tonnage 217 Built at Amsterdam When built 1831
 By whom built _____ Owners Messrs. J. & C.
 Port belonging to Londra Destined Voyage Spain
 If Surveyed Afloat or in Dry Dock Londra Dock

Original Survey, No. 1023 Port of Londra WAP Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topside	Masts, Yards, &c. <u>Good</u>
Spirketting	Wales	Sails <u>Not good</u>
Plank Shears	Counter	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of _____
Hatchway Comings	Rudder	Standing & Running Rigging <u>Good</u>
Breasthooks	Windlass	Copper

General Observations and Opinion, Is throughout in a very efficient state and may
 as required by the Instructions, continue in her present shape

Committee Minute 7th October 1842
 Character assigned 10 A 1

No. 320 Survey held at Londra Date October 5 1842
 on the Bk. William & George Master McDonnell
 Tonnage 144 Built at Amsterdam When built 1839
 By whom built _____ Owners Mr. Gordon
 Port belonging to Amsterdam Destined Voyage Spain
 If Surveyed Afloat or in Dry Dock Londra Dock

Original Survey, No. 320 Port of Londra WAP Classed 9 A 1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topside	Masts, Yards, &c.
Spirketting	Wales	Sails <u>Not good</u>
Plank Shears	Counter	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of <u>3</u>
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, Is in a very good state and may
 as required by the Instructions, continue in her present shape

Committee Minute 7th October 1842
 Character assigned 9 A 1

Lloyd's Register
 Foundation