

# ANNUAL SURVEYS.

9132

No. 168 Survey held at London Date October 8<sup>th</sup> 1842  
 on the Belhaaco Master braunford  
 Tonnage 229 Built at Wumbarton When built 1830  
 By whom built Reamy Owners Gilkinson  
 Port belonging to St. Glasgow Destined Voyage  
 If Surveyed Afloat or in Dry Dock Richies Dock

Original Survey, No. 168 Port of Glyde Nov 1838 Classed 3A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Good</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>Caulked good</u>
Spirkettling <u>Good</u>	Wales <u>Good</u>	Sails <u>Good</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Cables <u>Good</u>
Waterways <u>Good</u>	Plank and Treennails <u>Good</u>	Anchors No. of <u>3. 1. 1</u>
Hatchway Comings <u>Good</u>	Rudder <u>Good</u>	Standing & Running Rigging <u>Well maintained</u>
Breasthooks <u>Good</u>	Windlass <u>Good</u>	Copper <u>1842</u>

General Observations and Opinion, Has had new Engines of hull and lower part of stem in Hongkong  
 as required by the Instructions, At the present time shipped - new Engines of hull, stem and  
two new lower breast hooks - all the iron bolts put in at Hongkong) did not  
and replaced with copper - being caulked keel up and recoppered upon  
parts to Wale - she is now in a fit state for the conveyance of dry and suitable  
 Committee Minute 14<sup>th</sup> October 1843 Cargoes to and from all parts of the world and is  
 Character assigned F. 1 asterisk George Bayley

No. 143 Survey held at London Date October 8<sup>th</sup> 1842  
 on the B9 Margaret Master England  
 Tonnage 129 Built at Bideford When built 1835  
 By whom built Owners Bagin no change  
 Port belonging to Bideford Destined Voyage  
 If Surveyed Afloat or in Dry Dock Carver's Quay

Original Survey, No. 3258 Port of Bideford Nov. 1743 Classed 1A1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treennails	Anchors No. of
Hatchway Comings	(Outside to the Water's Edge.)	Standing & Running Rigging
Breasthooks	Rudder	Copper
	Windlass	

General Observations and Opinion, At the present 3 Stakes of Copper shipped off Copper comes - caulked from  
 as required by the Instructions, thence to top of Wale - 4 Stakes of new Copper put on - she is in  
a good and efficient condition to remain as classed 1A1  
 Committee Minute 14<sup>th</sup> October 1843 George Bayley  
 Character assigned 10/21 all