

ANNUAL SURVEYS.

No. 935^b Survey held at London Date Dec^r 16th 23rd 1842
 on the Baigun England Master Lewis
 Tonnage 425 Built at Chesham When built 1814
 By whom built _____ Owners Thos. Ward
 Port belonging to London Destined Voyage Home Lane
 & Surveyed At in Dry Dock Carters

Original Survey, No. 3983, 4180 Port of London Classed F. 1
6576, 7365, See Annexed Survey

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings <u>Loose</u>	Topsides	Masts, Yards, &c.
Spirketting	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, } This ship is quite adrift at the Stern beam fastenings
 as required by the Instructions, } also the Stern Hanging knees have worked, I am of
 opinion the Bolts are either broken or badly corroded. The Ceiling
 forward is in a very defective state, left a Card on the 18th Dec^r

Committee Minute 23rd December 1842

Character assigned _____

the general attention to the general state of the
 Ship. (20th Dec^r nothing is done to repair her)

Lloyd's Register
 Foundation

100614-0007