

REPORT of SURVEY for REPAIRS.

No. 157 Survey held at London Date Jan 4 184 3
 on the MS Morn Master Manning
 Tonnage 235 Built at Bristol When built 1775
 By whom built — Owners Donult
 Port belonging to London Destined Voyage Annua
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 970, 1664 Dated 3085, 3672, 3721, 4146, 4876, 7157, 7204, 8225, 9339, Classed F, 1
 Port London

REPAIRS

*The greater part -
 At present time new main Decks -*

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c. <u>Sufficient</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Sails <u>Good</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,


*In shifting the decks the beams proved
 very sound and good, is now fit for the conveyance
 of any and perishable cargo to and from all parts of
 the World and may remain as classed*

The Amount of Fee.....£ 1 : — : — is received by me, H. Manning

Committee's Minute 27th January 1843

Character assigned F, 1

LON614-0042



© 2019
 Lloyd's Register
 Foundation