

REPORT of SURVEY for REPAIRS.

Change of Owners

No. *155* Survey held at *London* Date *Feb 1st* 184 *3*
 on the *Bk Jane* Master *Buckland*
 Tonnage *301* Built at *New Brunswick* When built *1839*
 By whom built _____ Owners *J & J Raven*
 Port belonging to *Launceston* Destined Voyage *Launceston*
 If Surveyed Afloat or in Dry Dock *At Dock*

Original Survey, No. *5969, 6065* Dated *1530,* Classed *4 A 1*
 Port *London*
 REPAIRS *None*

Present Condition of the

Decks	Transoms <i>Sound</i>	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame <i>Sound & true</i>	Capstan
Lower Deck Beams & Fastenings	Topsides <i>Good</i>	Pumps
Spirkettling	Wales <i>"</i>	Masts, Yards, &c.
Plank Shears	Counter <i>"</i>	Sails <i>Good & Sufficient</i>
Waterways	Plank and Treenails (Outside to the Water's Edge) <i>"</i>	Cables
Hatchway Comings	Rudder <i>"</i>	Anchors No. of
Breasthooks	Copper <i>"</i>	Standing & Running Rigging

General Observations and Opinion, *Presents a very firm appearance and is in good condition to retain her present class*

The Amount of Fee.....£ 2 : — : — is received by me, *TH*

Committee's Minute *14th February* 18*43*

Character assigned *4 A 1*



© 2019

Lloyd's Register
Foundation

1000-41009