

ANNUAL SURVEYS.

9457

No. 23 Survey held at Sunderland Date Febry 14 1843
 on the By Mag delene Master D McLean
 Tonnage 263 Built at Sunderland When built 1840
 By whom built _____ Owners Goodson
 Port belonging to Sunderland Destined Voyage Pillau
 If Surveyed Afloat or in Dry Dock Afloat

Sunderland 1835
 Original Survey, No. 8847 Port of Sunderland Classed PAI

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	

General Observations and Opinion, Caulked & is in all respects in good condition & fit to
 as required by the Instructions, retain her present Class,

Committee Minute 17th February 1843

Character assigned PAI

No. 35 Survey held at Sunderland Date Febry 14 1843
 on the Sr Perzia Master Spencer
 Tonnage 120 Built at Yarmouth When built 1839
 By whom built _____ Owners Silva & Co
 Port belonging to Sunderland Destined Voyage Amsterdam
 If Surveyed Afloat or in Dry Dock Afloat

Yarmouth 312
 Original Survey, No. 8673 Port of Sunderland Classed PAI

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	

General Observations and Opinion, is in a very efficient state throughout and may retain
 as required by the Instructions, her present Class

Committee Minute 17th February 1843

Character assigned PAI



© 2019

Lloyd's Register
Foundation

L0104-0014