

# ANNUAL SURVEYS.

9463

No. 110 Survey held at London Date February 13 1842  
 on the Ship "Samarang" Master Alison  
 Tonnage 401 Built at London When built 1840  
 By whom built \_\_\_\_\_ Owners J & H L Pycram  
 Port belonging to London Destined Voyage Calcutta  
 Surveyed At or in Dry Dock Blackwall Yard

Original Survey, No. 7131, 8435 Port of London Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>not seen</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>"</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>Good &amp;</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>sufficient</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>"</u>

General Observations and Opinion,  
 as required by the Instructions,

*This ship is in good condition and  
 should remain as classed*

Committee Minute 21st February 1843

Character assigned 12 A 1

No. 117 Survey held at London Date Feb 14 1843  
 on the Barge "Asia" Master Tattersall  
 Tonnage 328 Built at Sunderland When built 1835  
 By whom built \_\_\_\_\_ Owners Munton  
 Port belonging to Sunderland Destined Voyage Sydney  
 Surveyed At or in Dry Dock Miss Fletcher

Original Survey, No. 226 Port of Sunderland, Lon 3826, Classed 9 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good when seen</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>"</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>Good &amp;</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>sufficient</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>Repaired</u>

General Observations and Opinion,  
 as required by the Instructions,

*At the present time Caretaker from the  
 copper up, & repaired the copper. The ship  
 is in good condition & should remain as*

Committee Minute 21 February 1843

Character assigned 9 A 1



© 2019

Lloyd's Register  
 Foundation