

# REPORT of SURVEY for REPAIRS.

*Change of Owners*

No. *1* Survey held at *London* Date *January 11<sup>th</sup>* 184*3*  
 on the *Bk Mary* Master *Grant*  
 Tonnage *533*<sup>463</sup> Built at *Sunderland* When built *1842*  
 By whom built \_\_\_\_\_ Owners *J. Boulton*  
 Port belonging to *London* Destined Voyage *New Zealand*  
 If Surveyed Afloat or in Dry Dock *St. Katharine's Dock*

Original Survey, No. *2123* Dated \_\_\_\_\_ Classed *9 A1*

Port *Sunderland*  
 REPAIRS *Caulked & sheathed with yellow metal over paper*

## Present Condition of the

|                               |  |                            |
|-------------------------------|--|----------------------------|
| Decks                         | Transoms   | Windlass                   |
| Upper Deck Beams & Fastenings | Timbers of the Frame                                 | Capstan                    |
| Lower Deck Beams & Fastenings | Topsides   | Pumps                      |
| Spirketting                   | Wales  | Masts, Yards, &c.          |
| Plank Shears                  | Counter  | Sails                      |
| Waterways                     | Plank and Treenails<br>(Outside to the Water's Edge) | Cables                     |
| Hatchway Comings              | Rudder   | Anchors No. of             |
| Breasthooks                   | <i>Copper</i> <i>Yellow Metal Decr 1842</i>          | Standing & Running Rigging |

General Observations and Opinion, *Appears in all respects eligible to retain her present Class*

The Amount of Fee.....£ *3* : : : is received by me, *LL*

Committee's Minute *21<sup>st</sup> February* 184*3*

Character assigned *9 A1*



© 2019

Lloyd's Register Foundation

LON 674-0129