

ANNUAL SURVEYS.

9547

No. 303 Survey held at London Date March 6th 1843
 on the Ship William Harris Master Watson
 Tonnage 342 Built at Whitby When built 1816
 By whom built _____ Owners Barry
 Port belonging to Whitby Destined Voyage Manama
 If Surveyed Afloat in Dry Dock Sancti Spiriti dock

Original Survey, No. 5 Port of Whitby, Lon 3333, 4055, Classed *A.1
6068, 6302, 8315

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms _____	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>fair</u>	Timbers of the Frame _____	Pumps _____
Lower Deck Beams & Fastenings _____	Topsides <u>Good</u>	Masts, Yards, &c. _____
Spirkettling _____	Wales _____	Sails _____
Plank Shears _____	Counter _____	Cables <u>Good &</u>
Waterways _____	Plank and Treenails _____ (Outside to the Water's Edge.)	Anchors No. of <u>sufficient</u>
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
Breasthooks <u>fair Good</u>	Windlass _____	Copper <u>Deposited</u>

General Observations and Opinion, At the present time, cut out Spout is several
as required by the Instructions, pieces in the Buttocks, above the wood sheathing
note to Mr Barry on the subject. I am of opinion that
the after part of the ship is not in that state of efficiency required
by the Rules, to maintain her present character
 Committee Minute 10th March 1843
 Character assigned 31st

Wm J Clark
28th March 1843
Wm J Clark
28th March 1843

No. 442 Survey held at London Date March 6th 1843
 on the Barque Trusty Master Oliver
 Tonnage 467 Built at Liverpool When built 1799
 By whom built _____ Owners Benson
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat in Dry Dock Patchlife cross dock

Original Survey, No. 214, 2665 Port of London Classed F.1
4123, 8103,

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms _____	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>fair</u>	Timbers of the Frame <u>not seen</u>	Pumps <u>Apparently poor</u>
Lower Deck Beams & Fastenings _____	Topsides <u>Good</u>	Masts, Yards, &c. _____
Spirkettling <u>Good</u>	Wales _____	Sails _____
Plank Shears _____	Counter _____	Cables <u>Good &</u>
Waterways <u>very good</u>	Plank and Treenails _____ (Outside to the Water's Edge.)	Anchors No. of <u>sufficient</u>
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
Breasthooks <u>fair</u>	Windlass _____	Copper _____

General Observations and Opinion, This ship is in very good condition for
as required by the Instructions, her class & deserves her present character

Committee Minute 10th March 1843
 Character assigned F.1
Wm J Clark
28th March 1843



© 2019

Lloyd's Register Foundation

Long 14-0210