

REPORT of SURVEY for REPAIRS.

9182

No. 162 Survey held at London Date November 19 & 22 1841
 on the Bk Bengal Merchant Master _____
 Tonnage 503 Built at Calcutta When built 1812
 By whom built _____ Owners _____
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 755, 2580 Dated _____ Classed A, 1 Asterisk
3910, 5580, expunged
 Port of London

REPAIRS At the present time Copper stripped off, part new Sheel & Foregrip,
 new false Sheel, under unhang, Pintles & Braces refastened, new fore
 piece of the lower breasthook refastened, caulked from the
 Sheel up, and sheathed with Copper
 New Foremast & the rigging was hauled

Present Condition of the

| Decks | Transoms | Windlass |
|-------------------------------|--|-------------------------------|
| Upper Deck Beams & Fastenings | Timbers of the Frame <u>sound when seen</u> | Capstan |
| Lower Deck Beams & Fastenings | Topsides | Pumps |
| Spirkettling | Wales | Masts, Yards, &c. <u>Good</u> |
| Plank Shears <u>Good</u> | Counter <u>Good</u> | Sails <u>Sufficient</u> |
| Waterways | Plank & Treenails (Outside to the Water's Edge) | Cables |
| Hatchway Comings | Rudder | Anchors No. of |
| Breasthooks | Copper | Standing & Running Rigging |

General Observations and Opinion, From her general good appearance, I am of opinion she
is fit for the safe conveyance of Dry & perishable cargoes
to & from all parts of the World and may within
her present Class A, 1 Asterisk

The Amount of Fee.....£ 3 : — : — is received by me, AB

Committee's Minute 25th October 1842

Character assigned A, 1 Asterisk