

REPORT of SURVEY for REPAIRS.

9202

No. 17 Survey held at London Date Oct 14th 1842
 on the Ship Zenobia Master Quen
 Tonnage 501 Built at Calcutta When built 1815
 By whom built _____ Owners Quen
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock Similar dock

Original Survey, No. 993, 1687 Dated 1, 2723, 3515, 4500, 5569, 6672, 8168, Classed * A. 1
 Port London

REPAIRS —

At the present time

*Renewed several Chain Bolts, the planks in way
 of the Bolts defective, cut out Spunk in pieces about
 3 1/2 inches square, for the bolts to pass through —*

Repaired the Copper

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,

*found a little movement along the bolts
 beams; left a Card calling attention to the state of the bolts
 beam fastenings, and recommended a few bolts should be drawn
 out for inspection. They also appear to be the original
 bolts, which has not been complied with —*

The Amount of Fee.....£ : : is received by me,

Committee's Minute 8th November 1842

Character assigned Fit

mitting



© 2019

Lloyd's Register
Foundation

LON 614-0281