

ANNUAL SURVEYS.

9236

No. 228 Survey held at London Date April 16 1842
 on the By James Master _____
 Tonnage 292 Built at Sunderland When built 1840
 By whom built _____ Owners C Walton
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Bullwharf Dock

Original Survey, No. 6926, Port of London 1840 Classed GA 1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps <u>Good</u>
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c. <u>See</u>
Spirkettling	Wales	Sails <u>Efficient</u>
Plank Shears	Counter	Cables <u>See</u>
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of <u>See</u>
Hatchway Comings	Rudder	Standing & Running Rigging <u>See</u>
Breasthooks	Windlass	Copper <u>1842</u>

General Observations and Opinion, Ship is sound and well equipped as before
 as required by the Instructions, In good and efficient condition for remaining
as classed GA 1

Committee Minute 18th November 1842

Character assigned GA 1

Special State of Copper 51.1

George Bayley

No. _____ Survey held at _____ Date _____ 184____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Original Survey, No. _____ Port of _____ Classed _____

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions,

Committee Minute _____ 184____

Character assigned _____



© 2019

Lloyd's Register
 Foundation

10614-0320