

REPORT of SURVEY for REPAIRS.

9245

No. 756 Survey held at London Date Nov 4th 1842
 on the Ag Anne Master Dryborough
 Tonnage 176 Built at Sunderland When built 1833
 By whom built _____ Owners Dryborough
 Port belonging to London Destined Voyage Export
 If Surveyed Afloat or in Dry Dock Stackwood's Dry Dock

Original Survey, No. 53,3301, Dated Jan 3 1842 Classed 10 A 1
 Port London 5680, 7499^x, 8368.

REPAIRS at the present time in consequence of damage
shipped - being carried keel up - and generally
overhauled - Keel up as before

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>842</u>	Standing & Running Rigging

General Observations and Opinion,

My opinion the damages are
efficiently repaired and the vessel is
eligible to remain as classed 10 A 1

George Bayley

The Amount of Fee.....£ : : is received by me,

Committee's Minute 25th November 1842

Character assigned 10 A 1

Damage

AB



© 2019

Lloyd's Register
Foundation

10464-0329