

ANNUAL SURVEYS.

9270

No. 431 Survey held at London Date Nov 28, Dec 3 1842
 on the Bk British March Master Taylor
 Tonnage 310 Built at Burton When built 1825
 By whom built _____ Owners J Graham
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Wart India Dock

Original Survey, No. 961, 1033 Port of London
5441, 6113, 7023, 7880, 9025
 The Surveyor is required to state the present Condition of the

Classed 10 A 1
 Rest. 40 7

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails <u>Watt found</u>
Plank Shears	Counter	Cables <u>too small</u>
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging <u>good</u>
Breasthooks	Windlass	Copper

General Observations and Opinion, Notice was left on board Nov 12th Dec 3rd 1842
 as required by the Instructions, the insufficiency of the Chain Cables which
have not been attended to

Committee Minute 6th December 1842

Character assigned 2

No. 378 Survey held at London Date Nov 30th 1842
 on the Bk London Master Mr Tait
 Tonnage 239 Built at Sunderland When built 1833
 By whom built _____ Owners Mr Tait - no change
 Port belonging to London Destined Voyage Singapore
 If Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 505, 220 Port of London
3705, 5302, 6525
 The Surveyor is required to state the present Condition of the

Classed 10 A 1

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails <u>good</u>
Plank Shears	Counter	Cables <u>good</u>
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of <u>Sufficient</u>
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, At the present time copper fastenings & Wale
 as required by the Instructions, & splices caulked and is in good condition to
retain her present shape

Committee Minute 6th December 1842

Character assigned 10 A 1

5520-0355