

# ANNUAL SURVEYS.

9270

No. 431 Survey held at London Date Nov 28, Dec 3 1842  
 on the Bk British March Master Taylor  
 Tonnage 310 Built at Burton When built 1825  
 By whom built \_\_\_\_\_ Owners J Graham  
 Port belonging to London Destined Voyage Jamaica  
 If Surveyed Afloat or in Dry Dock Wart India Dock

Original Survey, No. 911, 1033 Port of London  
5441, 6113, 7023, 7880, 9025  
 The Surveyor is required to state the present Condition of the

Classed 10 A 1  
 Rest. 40 7

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails <u>Wet found</u>
Plank Shears	Counter	Cables <u>too small</u>
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging <u>good</u>
Breasthooks	Windlass	Copper

General Observations and Opinion, Notice was left on board Nov 12<sup>th</sup> Dec 3<sup>rd</sup> 1842  
 as required by the Instructions, the insufficiency of the Chain Cables which  
have not been attended to

Committee Minute 6<sup>th</sup> December 1842

Character assigned 2

No. 378 Survey held at London Date Nov 30<sup>th</sup> 1842  
 on the Bk London Master Mr Tait  
 Tonnage 239 Built at Sunderland When built 1833  
 By whom built \_\_\_\_\_ Owners Mr Tait - no change  
 Port belonging to London Destined Voyage Singapore  
 If Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 505, 220 Port of London  
3705, 5302, 6525  
 The Surveyor is required to state the present Condition of the

Classed 10 A 1

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails <u>good</u>
Plank Shears	Counter	Cables <u>good</u>
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of <u>Sufficient</u>
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, At the present time copper fastenings & Wale  
 as required by the Instructions, & splices caulked and is in good condition to  
retain her present shape

Committee Minute 6<sup>th</sup> December 1842

Character assigned 10 A 1



5520-0355