

## ANNUAL SURVEYS.

9326

No. 278 Survey held at London Date 24 Dec 1842  
 on the Myatira Master Ramsey  
 Tonnage 298 Built at Sunderland When built 1840  
 By whom built — Owners Thompson  
 Port belonging to Sunderland Destined Voyage West Indies say Demerara  
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 1796 Port of Sunderland Classed 7A1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>good</u>	Capstan
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>"</u>	Pumps <u>good &amp; sufficient</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>"</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>good</u>	Wales <u>"</u>	Sails <u>"</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>yellow metal 1842 Feb?</u>

General Observations and Opinion,

as required by the Instructions, The yellow metal now raised two sheets  
is in good and efficient condition and may  
remain as classed

Committee Minute 30th December 1842

Character assigned 7A1

No. 253 Survey held at London Date 24 Dec 1842  
 on the At Catharine Elizabeth Master Merritt  
 Tonnage 399 Built at London When built 1833  
 By whom built Smith Owners Traders  
 Port belonging to London Destined Voyage St Vincent  
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 2703 Port of London Classed 11A1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>good</u>	Capstan
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>"</u>	Pumps <u>good</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>"</u>	Masts, Yards, &c. <u>unfouled</u>
Spirkettling <u>good</u>	Wales <u>"</u>	Sails <u>sufficient</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>1830 see back of report</u> <u>1842 Feb</u>

General Observations and Opinion,

as required by the Instructions, is in good and efficient condition  
and may be continued as classed

Committee Minute 30th December 1842

Character assigned 11A1



© 2019

Lloyd's Register  
Foundation

10N619-0413



GP meeting to appear  
which is necessary

The Owners has called at the  
office and stated the  
within ship to have been

captured in 1829

Officer

9/10/1829



© 2019

Lloyd's Register  
Foundation