

9592
43

If Surveyed Afloat or in Dry Dock New Name Vangs

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirketting	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, *Am long Breast Hook fitted 'ween Decks - Caulked from
as required by the Instructions, the Copper up and many graving pieces put into the
Plank of the Topside - Upper Course Wood sheathed - In my
opinion she may remain as classed for the present* *GA 174*
Committee Minute *24th March 1843* *Free 1 p.m.*
Character assigned *J A 1* *George Bayley*

No. Survey held at London Date Jan 25 Feb 4. 7. 14 1843
on the Bj Red Fort Master Gibben
Tonnage 174 Built at Garnouth When built 1830
By whom built Owners Gibben
Port belonging to London Destined Voyage Spain
If Surveyed Afloat or in Dry Dock at Newbram Dock

Original Survey, No. _____ Port of London March 1840 _____ Classed 3A1

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettig	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, In consequence of damage 2 pms in Charleshen 8 Stanchions
as required by the Instructions, 1 Gun but head & another shifted, Cautioned kept up - being.
In my opinion she is eligible to remain as elapsed
Contd/341 George Bayley.

Committee Minute _____ 184

Character assigned _____