

ANNUAL SURVEYS.

9601
H

No. 335 Survey held at London Date March 21st 1843
on the Brig Lively Master Martyn
Tonnage 166 Built at Dumbarton When built 1832
By whom built _____ Owners Martyn
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Fountain ways

Scupper 1493,
Original Survey, No. 4457, 4503, Port of London February 1842 Classed Cout 8 A
6710, 6928, 8456,
The Surveyor is required to state the present Condition of the 3A1
1040

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

Good fair Good fair Good fair
Requires caulking
Good
200
Expd 1843

General Observations and Opinion, key open and stuck aloft left a card recommending
as required by the Instructions, that the Topsides and Wales should be caulked throughout
since 6. to this date the Topsides
have not been caulked
in 20 - The Topsides are
now caulked 9.13-
Committee Minute 31st March 1843
21st April
Character assigned 10 A
not in my opinion eligible for the Courageance
notice of dry & perishable Cargoes & their character should
be made & repeated until the useful repairs are done
George Bayley

No. 27 Survey held at London Date March 21 1843
on the Schooner Lady Rebou Master Blythe
Tonnage 57 Built at Wienhoe When built 1836
By whom built _____ Owners Capt H
Port belonging to Leicester Destined Voyage St Michael
If Surveyed Afloat or in Dry Dock Fountain ways

Scupper 87,
Original Survey, No. 7121, 9202, Port of London Jan 7 1841 Classed 10 A

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

Good Good Good
Good
Good
Good

General Observations and Opinion, Repaired Copper - In my opinion this is eligible
as required by the Instructions, to remain as classed 10 A
George Bayley
Committee Minute 31st March 1843
Character assigned 10 A