

REPORT of SURVEY for REPAIRS.

Change of Owners

No. *836* Survey held at *London* Date *March 14* 184*3*
on the *Bg Arab* Master *H. C. Cayzer*
Tonnage *265* Built at *Sunderland* When built *1840*
By whom built _____ Owners *Dunsford*
Port belonging to *London* Destined Voyage *Valparaiso*
If Surveyed Afloat or in Dry Dock *London Dock*

By Sunderland 1511,
Original Survey, No. *7936, 8354* Dated _____

Classed *7A1*

Port *of London*

REPAIRS *In good condition*

Present Condition of the

Decks	Transoms <i>Sound</i>	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame <i>sound when seen</i>	Capstan
Lower Deck Beams & Fastenings	Topsides <i>Good</i>	Pumps
Spirkettling	Wales <i>"</i>	Masts, Yards, &c. <i>Good & sufficient</i>
Plank Shears	Counter <i>"</i>	Sails
Waterways	Plank and Treenails <i>Good</i> (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder <i>"</i>	Anchors No. of
Breasthooks	Copper <i>"</i>	Standing & Running Rigging

General Observations and Opinion, *Appears in all respects in good & efficient condition so remain in her present shape*

W. W. W. W.

The Amount of Fee.....£ *1* : - : - is received by me, *W. W. W. W.*

Committee's Minute *15th April* 184*3*

Character assigned *7A1*

W. W. W. W.

